

## **Utility Box Information**

The utility boxes and pedestals do not receive regular inspections. Technicians repair them on an as needed basis when they receive notification from residents, or if they are in the area working on other projects.

Due to the age, many of the utility boxes are rusting, leaning or have exposed wires. It is recommended that you contact the specific utility and they will direct you to the correct 800 number to call. If you do not receive a timely response contact Troy Senior Engineer, Anthony Cicchetti, [A.Cicchetti@troymi.gov](mailto:A.Cicchetti@troymi.gov) for additional assistance.